ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0329, W0337, W0331, W0339, W0343, W0364, W0341, W

Street Name
Lakshmi Sagar Lyt North Side, 1st Cre, NA, Lakshmi Sagar Lyt 6th Cre, Lakshmi Sagar Lyt, 5th Cre

Significant Landmark
Bagalagunte (Gowdike hola) (ಜೋಡಿದಾರ ನರಸಿಂಹಯ್ಯ)

Segment No.
14/C-W0329/S120327

Total Length (m)
393.13

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	16.08	77.501280	13.058985	77.501320	13.058983	9th cross	Dead end
2	37.09	77.500738	13.059394	77.500681	13.059063	9th cross	Dead end
3	39.46	77.500975	13.059412	77.500933	13.059058	9th cross	Dead end
4	41.53	77.501192	13.059399	77.501144	13.059027	9th cross	Dead end
5	36.31	77.501409	13.059329	77.501366	13.059003	9th cross	Dead end
6	38.45	77.501606	13.059337	77.501577	13.058990	9th cross	Dead end
7	42.32	77.501820	13.059347	77.501778	13.058967	9th cross	Dead end
8	141.89	77.501981	13.058920	77.500679	13.059045	MEI Layout	Dead end 6th cross

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements of CC roads drains and other works at Gowdike hola (Jodidar Narasimaiah layout) in ward No 14 Bagalagunte

Sanctioned Estimated Amount (Rs.)
10000000

Sanctioned Year
19-20

Year
2019 - 2020

Type of Work
Others

Other Work Type
CC road and Drain

Tender
Not a Tender

Work Details

Job No. / Work Code
014-20-000112

Work Order No.
EE/DD/WO/02/20-21

Work Order Date
04/04/2020

Period of Extention

Defect Liability Period From
04/04/2020

Defect Liability Period To
03/04/2021

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0329, W0337, W0331, W0339, W0343, W0364, W0341, W

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073.

Scanned by CamScanner

Bruhat Bangalore Mahan...

...ERING DEPARTMENT

... Sheet

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.D.L		9994236.00
Phone No.	**E-Mail ID**	
7483661463		

Field Inspection Details

Number of Trees	Any Other Information	Name
0	CC Road	Chetan K M
Date of Inspection	**Remarks**	
07/08/2020	works complete	

Category	Image	Photo Remark
Drain Condition		
Footpath Condition		
Road Condition		
Segment End		
Segment Start		

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE-DAS	10/08/2020	06/09/2020	Approved.
EE	K.S Idrus	07/08/2020	06/09/2020	Completed
AEE	M B Jayakumar	07/08/2020	06/09/2020	works complete
AE	M B jayakumar	07/08/2020	06/09/2020	works complete
AE	Chetan K M	07/08/2020	06/09/2020	Completed

Improvements of ce roads, drains and other works at Gowdke hola (Todidar Narasimaiah Layout) in ward no:14, Bagalagunte.

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0329, W0337, W0331, W0339,

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073.

Scanned by CamScanner